

PRESSOTHERAPY MACHINE

Air Wave Presso Therapy: BS-PR11



Specifications:

Parameter	Value
Power	AC220V/50Hz, < 250W
Pannello controllo	Colorful LCD screen
Temperatura infrarosso	35 – 60 C degrees
Airwave Intensity	1 – 7 Levels
N. Camere	2 chambers on each arm 4 chambers on the waist 3 chambers on each leg
Peso	< 15Kg